

[Skip to content](#)



## Product Safety Recalls Australia

Advanced recall search

### Maintenance View - GM Holden Ltd--RG Colorado & RG Colorado 7 [DW - 23 Apr, 2015 17:39:29 onwards]

version item display action log diff security xml relations audit trail Version: Maintenance

Version:  ▼

Display:  as content  in a list  as a hyperlink

## GM Holden Ltd--RG Colorado & RG Colorado 7

PRA number: 2015/14657

Date published: 23<sup>rd</sup> April 2015

### Product information

#### Product description

2014 & 2015 RG Colorado Crew Cab, Single Cab, Space Cab, and RG Colorado 7 SUV

#### Identifying features

- MY2014 to MY2015 Holden RG Colorado & RG Colorado 7
- Affected Build Range is from MMU145DK0EH600244 to MMU156FK0FH616228
- Affected Production Dates: 04 SEP 2013 to 21 JAN 2015

#### What are the defects?

The Alternator B+ Electrical Cable may have been assembled in contact with a steel bracket at the battery tray. Under certain driving conditions the insulation on the cable may wear, resulting in the potential for an electrical short circuit to develop between the cable and the bracket.

#### What are the hazards?

If the defect occurs, there is a risk that the cable insulation may melt or catch fire, which may pose a risk of injury to the vehicle occupant(s) and other road users.

#### Where the product was sold

- Nationally

#### Traders who sold this product

All Holden dealers nationally

#### Supplier

GM Holden Ltd

### What should consumers do?

Holden will write to all affected customers to notify them of the required action.

#### Private information

#### Number of unique products

2

#### Quantity affected

26254

### Initiated

Regulator contacted supplier in relation to the product/s prior to deciding to recall?

No

### Product details

Product is supplied with a warranty registration card or an online registration option

Unknown

### Supply chain

#### Supply chain position(s)

- Importer / Distributor / Wholesaler

#### Product's country of origin

Thailand

Processes/mechanisms are in place to track the product through the supply chain

Yes

### Injuries

#### Known injuries or damage

There have been 7 reports of fire damage but no reports of related injuries resultant of this condition

### Recall advertising

#### Publicity action

This recall will not be advertised. All customers of our vehicles that are within the affected range will be notified via customer letters in accordance with the FCAI "Code of Practice for the Conduct of an Automotive Safety Recall".

Consumers are offered incentives to return the product (e.g. cash, gift card, discount)

No

**Supplier details**

**Contact details**

Name: [Redacted]  
Phone 1: [Redacted]  
Email: [Redacted]

**Nominated representative contact details**

Name: Holden Customer Care  
Phone 1: 1800632826

**Staff entered data**

**Administratively closed**

No

**Recall type**

MotorVehicle

**Regulator(s)**

Department of Infrastructure and Regional Development (DIRD) [edit]

**Home regulator(s)**

Department of Infrastructure and Regional Development (DIRD) [edit]

**Product classification**

1.04.01 Passenger car (GPC: 77000000)

**Staff only**

Date created: 21<sup>st</sup> April 2015

Date first published: 23<sup>rd</sup> April 2015

**Initial assessment**

**Hazard**

Not entered

**Risk**

Not entered

**Final assessment**

**Hazard**

Not entered

**Risk**

Not entered

**Level of recall**

Consumer

**Progress Reports**

Progress report reminders enabled: No

Next progress report due: 21<sup>st</sup> June 2015

Reminder sent: Never

No progress reports submitted for this recall

**Staff Actions**

No actions have been recorded for this recall.

**Add action**

**Close this recall?**

If you are the regulator responsible for this recall and you need to close it then please enter the product success rate and optionally a description of what the success rate means and click the 'Close recall' button.

Success rate:  %

Success rate description: